

SERVICE INSTALLATION CHECKLIST

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 9/3/2013, 9/4/2013, 9/5/2013	Man Days: 3
Inspection Unit: Jacksonville	
Location of Audit: Jacksonville	
Exit Meeting Contact: Rodger Camerer	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION		
Location of Construction: 327 West Lafayette Avenue, Jacksonville, Illinois	Construction Performed By: Ameren Illinois	
Contractor Foreman:	No contractor on the job site.	
Operator Inspector:	John Sigler	
Person(s) On Job Site		
Scott Grogan	Bobby Joe Brown	
Description of Construction: Ameren Illinois was digging up isolated steel risers and changing them with new plastic risers.		

SERVICE INSTALLATION		Status
[192.55]	Steel	No
<u>General Comment:</u> <i>The service line is plastic with a steel riser.</i>		
[192.59]	PE	Yes
[192.59]	Other	No
[192.619,192.621,192.623]	MAOP	30 psig
[192.5]	Class location :	Class 2

SERVICE INSTALLATION CHECKLIST

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.53]	Are components qualified for use?	Satisfactory
[192.63(a)(2)]	Pipe Size :	1/2" Plastic
[192.55,192.59]	Specification :	ASTM D 2513
[192.55,192.59]	Manufacturer :	Driscopex
[192.55,192.59]	Pipe Grade :	PE 2406/2708
[192.55,192.59]	Wall Thickness :	.090
[192.63]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
[192.227]	Welder qualification date:	Not Applicable
<u>General Comment:</u> <i>No welding was done on this job site.</i>		
[192.227]	Welder's Name:	Not Applicable
<u>General Comment:</u> <i>No welding was done on this job site.</i>		
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Satisfactory
[192.285]	Date of Qualification :	01-21-2013
[192.285]	Joiner's name:	Scott Grogan
[192.455]	Is buried metallic pipe coated?	Not Applicable
<u>General Comment:</u> <i>The pipe that was installed was plastic.</i>		
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
<u>General Comment:</u> <i>The pipe that was installed was plastic.</i>		
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
<u>General Comment:</u> <i>The pipe that was installed was plastic.</i>		
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
<u>General Comment:</u> <i>The pipe that was installed was plastic.</i>		
[192.461]	Does coating meet 192.461?	Not Applicable
<u>General Comment:</u> <i>This is an all plastic system area.</i>		

SERVICE INSTALLATION CHECKLIST

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
<u>General Comment:</u> <i>The pipe that was installed was plastic.</i>		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Satisfactory
<u>General Comment:</u> <i>The meter set area is all painted.</i>		
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
<u>General Comment:</u> <i>No other underground structures in this area.</i>		
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
[192.321]	Does plastic pipe have means of locating while underground?	Satisfactory
[192.325]	Are required clearances from underground structures being maintained?	Not Applicable
<u>General Comment:</u> <i>No other underground structures in this area.</i>		
Is required cover being obtained for the service line?		Satisfactory
[192.503]	Are general testing requirements being met?	Satisfactory
[192.517]	Are records being made of strength and leak tests?	Satisfactory
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
[192.805(c)]	Were non-qualified personnel being "directed and observed" by a qualified individual?	Satisfactory
[192.805(c)]	Were span of control limitations being followed?	Satisfactory
Was a Protocol 9 (Form 15) Completed?		No
[192.614]	Were One Call Notifications performed as required?	Satisfactory
[192.614]	Dig Ticket #	X2400606
[192.383(b)]	Is an EFV installed on any new or replaced service line serving a single-family residence?	
<u>General Comment:</u> <i>The service line was dug up at the house riser only.</i>		

SERVICE INSTALLATION CHECKLIST

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.